


# What is the condition of 23rd Avenue today?

- Potholes
- Narrow, substandard lanes
- No left turn lanes at key intersections
- Narrow and uneven sidewalks
- Inadequate buffer between vehicles and pedestrians



# Who uses the 23rd Avenue corridor?

- 13,400-20,000 vehicles per day
- More than 6,000 daily transit riders – one of Metro's top 10 highest ridership routes
- Pedestrians and bike riders
- Residents, businesses and commuters

